



13251 E CONTROL TOWER RD  
 FAA CRS #OMKR399L  
 Englewood CO 80112  
 Voice Main: 303-799-8906  
 Voice Parts: 303-799-1866  
 Main Fax: 303-799-0634  
 Parts Fax: 303-799-3885

[www.StraightFlight.com](http://www.StraightFlight.com)  
 Tax ID: 84-1065675

# INVOICE

Print Date : Mar-31-2021 3:41 PM Printed By : Kathryn Sielsky Print No. : 2

**Your P.O.: PO-PA-1305** **No. : 37821** Pg:1/7

<b>Bill To :</b> Peregrine 7385 S. Peoria Street Unit C4 Englewood, CO 80112 United States Tel. : 303-325-3873 Fax : 720-862-3840	<b>Shipped To : [PEREGRINAVIO]</b> Peregrine 7385 S. Peoria Street Unit C4 Englewood, CO 80112 United States Tel. : 303-325-3873 Fax : 720-862-3840
--	--

MNT W/O No. : 10384	Our Ref : MODIFICATION 10384	Domestic AWB :
Customer P.O. : PO-PA-1305	Your Ref : N150GV	Int'l AWB :
Invoice Date : Mar-31-2021	Project : FLAP ACTUATOR HEATER S	Origin :
Due Date : Apr-30-2021	Contract :	Transport :
Ship Via :	License No. : N/A	Nationality:
F.O.B. : ORIGIN	Expires : N/A	Trip/Flight :
Shipped Date : Mar-31-2021	Terms : NET 30	
Aircraft Model : G150	ID : N150GV	Tail/Reg No.: N150GV
		Serial : 201
Model Description : G150		
Maintenance Description : FLAP ACTUATOR HEATER STC		

Line	Detail Of Charges	Cnd	Qty Ordered	Shipped	Unit Sell Price	Amount
1	Scope : [001] Card No. : [001] ADMIN					
	Labor, Standard, In House Summary Charge (Regular) Note: [ 03:00 HR ]		1.00EA	1.00	\$ 315.00000 EA	\$ 315.00
	Scope : [001] Card No. : [002] INDUCTION INSPECTION					
2	Labor, Standard, In House Summary Charge (Regular) Note: [ 08:28 HR ]		1.00EA	1.00	\$ 889.00000 EA	\$ 889.00
	Scope : [001] Card No. : [003] REMOVED/REINSTALLED INTERIOR INCLUDING FLOORBOARDS					
3	Labor, Standard, In House		1.00EA	1.00	\$ 3,442.25000 EA	\$ 3,442.25

Continued on next page...



13251 E CONTROL TOWER RD  
 FAA CRS #OMKR399L  
 Englewood CO 80112  
 Voice Main: 303-799-8906  
 Voice Parts: 303-799-1866  
 Main Fax: 303-799-0634  
 Parts Fax: 303-799-3885

[www.StraightFlight.com](http://www.StraightFlight.com)  
 Tax ID: 84-1065675

# INVOICE

Print Date : Mar-31-2021 3:41 PM Printed By : Kathryn Sielsky Print No. : 2

Our Ref : MODIFICATION 10384 Project : FLAP ACTUATOR HEATER S Sales Invoice No. 37821 Page:2/7  
 Your Ref : N150GV

Line	Detail Of Charges	Cnd	Qty Ordered	Shipped	Unit Sell Price	Amount
	Summary Charge (Regular) Note: [ 32:47 HR ]					
	Scope : [001] Card No. : [004] DEACTIVATED STANDBY LIGHTING PWR SUPPLIES					
4	Labor, Standard, In House Summary Charge (Regular) Note: [ 00:30 HR ]		1.00EA	1.00	\$ 52.50000 EA	\$ 52.50
	Scope : [001] Card No. : [005] VERIFIED SPARE CONDUIT BEHIND GALLEY INSTALLATION					
5	Labor, Standard, In House Summary Charge (Regular) Note: [ 02:00 HR ]		1.00EA	1.00	\$ 210.00000 EA	\$ 210.00
	Scope : [001] Card No. : [006] LOCATED SLAT POSITION IN RETRACT POSITION					
6	Labor, Standard, In House Summary Charge (Regular) Note: [ 01:43 HR ]		1.00EA	1.00	\$ 180.25000 EA	\$ 180.25
	Scope : [001] Card No. : [007] MEASURED SLAT POSITION WITH ACTUATORS EXTENDED					
7	Labor, Standard, In House Summary Charge (Regular) Note: [ 00:30 HR ]		1.00EA	1.00	\$ 52.50000 EA	\$ 52.50
	Scope : [001] Card No. : [008] REMOVED & REINSTALLED LH/RH SLAT ACCESS PANELS					
8	NAS1581A4T3 Screw	NE	2.00EA	2.00	\$ 3.09140 EA	\$ 6.18
9	NAS1581F3T3 Screw	NE	20.00EA	20.00	\$ 1.19600 EA	\$ 23.92
10	Labor, Standard, In House Summary Charge (Regular) Note: [ 15:29 HR ]		1.00EA	1.00	\$ 1,625.75000 EA	\$ 1,625.75
	Scope : [001] Card No. : [009] REMOVED & REINSTALLED SLATS					
11	AN5-24	NE	2.00EA	2.00	\$ 1.12580 EA	\$ 2.25

Continued on next page...



13251 E CONTROL TOWER RD  
 FAA CRS #OMKR399L  
 Englewood CO 80112  
 Voice Main: 303-799-8906  
 Voice Parts: 303-799-1866  
 Main Fax: 303-799-0634  
 Parts Fax: 303-799-3885

[www.StraightFlight.com](http://www.StraightFlight.com)  
 Tax ID: 84-1065675

# INVOICE

Print Date : Mar-31-2021 3:41 PM Printed By : Kathryn Sielsky Print No. : 2

Our Ref : MODIFICATION 10384 Project : FLAP ACTUATOR HEATER S Sales Invoice No. 37821 Page:3/7  
 Your Ref : N150GV

Line	Detail Of Charges	Cnd	Qty Ordered	Shipped	Unit Sell Price	Amount
12	Bolt Labor, Standard, In House Summary Charge (Regular) Note: [ 06:32 HR ]		1.00EA	1.00	\$ 686.00000 EA	\$ 686.00
	Scope : [001] Card No. : [010] MEASURED SLAT ACTUATOR JACK SCREWS					
13	Labor, Standard, In House Summary Charge (Regular) Note: [ 01:07 HR ]		1.00EA	1.00	\$ 117.25000 EA	\$ 117.25
	Scope : [001] Card No. : [011] REMOVED/REINSTALLED LH/RH WING TO BODY FAIRINGS					
14	NAS1581C3T3 SCREW	NE	20.00EA	20.00	\$ 0.94900 EA	\$ 18.98
15	Labor, Standard, In House Summary Charge (Regular) Note: [ 16:53 HR ]		1.00EA	1.00	\$ 1,772.75000 EA	\$ 1,772.75
	Scope : [001] Card No. : [012] REMOVED/REINSTALLED LH/RH WING TOP LANDGEAR PANELS					
16	Labor, Standard, In House Summary Charge (Regular) Note: [ 03:20 HR ]		1.00EA	1.00	\$ 350.00000 EA	\$ 350.00
	Scope : [001] Card No. : [014] DISCONNECTED/RECONNECTED LH/RH AILERON CTRL TUBES					
17	Labor, Standard, In House Summary Charge (Regular) Note: [ 04:15 HR ]		1.00EA	1.00	\$ 446.25000 EA	\$ 446.25
	Scope : [001] Card No. : [015] REMOVED/REINSTALLED LWR FUSELAGE PANELS					
18	MS21076-3N NUTPLATE	NE	1.00EA	1.00	\$ 2.79500 EA	\$ 2.80
19	CCR264SS-3-4 Cherry Rivet	NE	2.00EA	2.00	\$ 0.20800 EA	\$ 0.42
20	Labor, Standard, In House Summary Charge (Regular) Note: [ 06:36 HR ]		1.00EA	1.00	\$ 693.00000 EA	\$ 693.00

Continued on next page...



13251 E CONTROL TOWER RD  
 FAA CRS #OMKR399L  
 Englewood CO 80112  
 Voice Main: 303-799-8906  
 Voice Parts: 303-799-1866  
 Main Fax: 303-799-0634  
 Parts Fax: 303-799-3885

[www.StraightFlight.com](http://www.StraightFlight.com)  
 Tax ID: 84-1065675

# INVOICE

Print Date : Mar-31-2021 3:41 PM Printed By : Kathryn Sielsky Print No. : 2

Our Ref : MODIFICATION 10384 Project : FLAP ACTUATOR HEATER S Sales Invoice No. 37821 Page :4/7  
 Your Ref : N150GV

Line	Detail Of Charges	Cnd	Qty Ordered	Shipped	Unit Sell Price	Amount
	Scope : [001] Card No. : [016] REMOVED/REINSTALLED	FWD	END OF GALLEY FOM			
21	Labor, Standard, In House Summary Charge (Regular) Note: [ 06:00 HR ]		1.00EA	1.00	\$ 630.00000 EA	\$ 630.00
	Scope : [001] Card No. : [017] INSTALLED FLAP/SLAT ACTUATOR HEAT SYSTEM STC					
22	MS25036-108 Terminal	NE	2.00EA	2.00	\$ 0.49400 EA	\$ 0.99
23	FSAHS Heated Flap STC Kit	NE	1.00EA	1.00	\$ 4,279.09300 EA	\$ 4,279.09
24	FREIGHT Inbound Freight AWB 949893760433	NE	1.00EA	1.00	\$ 15.93800 EA	\$ 15.94
25	HL18PB-5-5 Hi loc pin	NE	1.00EA	1.00	\$ 0.66300 EA	\$ 0.66
26	HL70-5 Hi-Loc Collar	NE	1.00EA	1.00	\$ 0.52000 EA	\$ 0.52
27	MS21919DG12 Clamp	NE	1.00EA	1.00	\$ 1.04000 EA	\$ 1.04
28	Labor, Standard, In House Summary Charge (Regular) Note: [ 130:04 HR ]		1.00EA	1.00	\$ 13,657.00000 EA	\$ 13,657.00
	Scope : [001] Card No. : [018] FABRICATE/INSTALL FLAP/SLAT HEAT CTRL BOX MNT BRKT					
29	NAS1581C3R3 Screw	NE	10.00EA	10.00	\$ 1.23500 EA	\$ 12.35
30	MS21059L3 Nutplate/Double Wing Floater	NE	4.00EA	4.00	\$ 1.09433 EA	\$ 4.38
31	MS27039-1-07 Screw Kit	NE	4.00EA	4.00	\$ 0.15600 EA	\$ 0.62
32	NAS1149F0332P Washer	NE	4.00EA	4.00	\$ 0.06500 EA	\$ 0.26
33	MS21059L08 Nutplate/Double Wing Floater	NE	4.00EA	4.00	\$ 0.32500 EA	\$ 1.30
34	Labor, Standard, In House		1.00EA	1.00	\$ 1,022.00000 EA	\$ 1,022.00

Continued on next page...



13251 E CONTROL TOWER RD  
 FAA CRS #OMKR399L  
 Englewood CO 80112  
 Voice Main: 303-799-8906  
 Voice Parts: 303-799-1866  
 Main Fax: 303-799-0634  
 Parts Fax: 303-799-3885

[www.StraightFlight.com](http://www.StraightFlight.com)  
 Tax ID: 84-1065675

# INVOICE

Print Date : Mar-31-2021 3:41 PM Printed By : Kathryn Sielsky Print No. : 2

Our Ref : MODIFICATION 10384 Project : FLAP ACTUATOR HEATER S Sales Invoice No. 37821 Page :5/7  
 Your Ref : N150GV

Line	Detail Of Charges	Cnd	Qty Ordered	Shipped	Unit Sell Price	Amount
	Summary Charge (Regular) Note: [ 09:44 HR ]					
	Scope : [001] Card No. : [019] INSTALLED FLAP/SLAT ACTUATOR HEAT SYS CTRL SWITCH					
35	Labor, Standard, In House Summary Charge (Regular) Note: [ 06:26 HR ]		1.00EA	1.00	\$ 675.50000 EA	\$ 675.50
	Scope : [001] Card No. : [020] PRINTED WIRING					
36	Labor, Standard, In House Summary Charge (Regular) Note: [ 13:43 HR ]		1.00EA	1.00	\$ 1,440.25000 EA	\$ 1,440.25
	Scope : [001] Card No. : [021] INSTALL CB, CTRL SWITCH,ANNUNCIATORS,OVERLAYPANELS					
	<u>Corrective Action</u> Additional wire routing required due to CB relocation.					
37	MODIFICATION Modify CB Overlay 25G3521250-505	NE	1.00EA	1.00	\$ 630.50000 EA	\$ 630.50
38	FREIGHT Return Freight for CB Overlay Modification	NE	1.00EA	1.00	\$ 123.50000 EA	\$ 123.50
39	FREIGHT Outbound Freight for CB Overlay Modification	NE	1.00EA	1.00	\$ 255.69700 EA	\$ 255.70
40	MS25036-111 Terminal	NE	4.00EA	4.00	\$ 0.67600 EA	\$ 2.70
41	MS25036-111 Terminal	NE	2.00EA	2.00	\$ 0.67600 EA	\$ 1.35
42	Labor, Standard, In House Summary Charge (Regular) Note: [ 16:06 HR ]		1.00EA	1.00	\$ 1,690.50000 EA	\$ 1,690.50
	Scope : [001] Card No. : [022] REMOVED/REINSTALLED LH/RH LAND LIGHTS FOR ACCESS					
43	Labor, Standard, In House Summary Charge (Regular) Note: [ 00:49 HR ]		1.00EA	1.00	\$ 85.75000 EA	\$ 85.75

Continued on next page...



13251 E CONTROL TOWER RD  
 FAA CRS #OMKR399L  
 Englewood CO 80112  
 Voice Main: 303-799-8906  
 Voice Parts: 303-799-1866  
 Main Fax: 303-799-0634  
 Parts Fax: 303-799-3885

[www.StraightFlight.com](http://www.StraightFlight.com)  
 Tax ID: 84-1065675

# INVOICE

Print Date : Mar-31-2021 3:41 PM Printed By : Kathryn Sielsky Print No. : 2

Our Ref : MODIFICATION 10384 Project : FLAP ACTUATOR HEATER S Sales Invoice No. 37821 Page:6/7  
 Your Ref : N150GV

Line	Detail Of Charges	Cnd	Qty Ordered	Shipped	Unit Sell Price	Amount
	Scope : [001] Card No. : [023] FAB/INSTALL LWR FUSELAGE CTRL MNT BRKT & RELAY					
44	HL70-5 Hi-Loc Collar	NE	14.00EA	14.00	\$ 0.52000 EA	\$ 7.28
45	HL18PB-5-4 Hi Lock pin-protruding shear	NE	12.00EA	12.00	\$ 1.06600 EA	\$ 12.79
46	HL18PB-5-5 Hi loc pin	NE	2.00EA	2.00	\$ 0.66300 EA	\$ 1.33
47	Labor, Standard, In House Summary Charge (Regular) Note: [ 03:03 HR ]		1.00EA	1.00	\$ 320.25000 EA	\$ 320.25
	Scope : [001] Card No. : [024] INSTALLED WIRING FROM COCKPIT TO MID-CABIN					
48	Labor, Standard, In House Summary Charge (Regular) Note: [ 16:00 HR ]		1.00EA	1.00	\$ 1,680.00000 EA	\$ 1,680.00
	Scope : [001] Card No. : [025] INSTALLED FLAP/SLAT WIRING HARNESS FROM CTRL BOX					
49	Labor, Standard, In House Summary Charge (Regular) Note: [ 07:36 HR ]		1.00EA	1.00	\$ 798.00000 EA	\$ 798.00
	Scope : [001] Card No. : [026] INSTALLED FLAP/SLAT ACTUATOR HEAT ELEMENTS					
50	Labor, Standard, In House Summary Charge (Regular) Note: [ 06:59 HR ]		1.00EA	1.00	\$ 733.25000 EA	\$ 733.25
	Scope : [001] Card No. : [027] FLAP/SLAT HEATER STC POST MOD OPERATIONAL CHECK					
51	Labor, Standard, In House Summary Charge (Regular) Note: [ 01:01 HR ]		1.00EA	1.00	\$ 106.75000 EA	\$ 106.75
	Scope : [001] Card No. : [028] VERIFIED SLAT ACTUATOR POSITIONS AFT MOD					
52	Labor, Standard, In House		1.00EA	1.00	\$ 105.00000 EA	\$ 105.00

Continued on next page...



13251 E CONTROL TOWER RD  
 FAA CRS #OMKR399L  
 Englewood CO 80112  
 Voice Main: 303-799-8906  
 Voice Parts: 303-799-1866  
 Main Fax: 303-799-0634  
 Parts Fax: 303-799-3885

[www.StraightFlight.com](http://www.StraightFlight.com)  
 Tax ID: 84-1065675

# INVOICE

Print Date : Mar-31-2021 3:41 PM Printed By : Kathryn Sielsky Print No. : 2

Our Ref : MODIFICATION 10384 Project : FLAP ACTUATOR HEATER S Sales Invoice No. 37821 Page : 7/7  
 Your Ref : N150GV

Line	Detail Of Charges	Cnd	Qty Ordered	Shipped	Unit Sell Price	Amount
	Summary Charge (Regular) Note: [ 01:00 HR ]					
	Scope : [001] Card No. : [029] TOUCHED-UP PAINT AS REQUIRED					
53	PAINT[1] Paint	NE	1.00EA	1.00	\$ 153.52000 EA	\$ 153.52
54	PAINT[2] Supplies	NE	1.00EA	1.00	\$ 46.06000 EA	\$ 46.06
55	Labor, Standard, In House Summary Charge (Regular) Note: [ 15:47 HR ]		1.00EA	1.00	\$ 1,657.25000 EA	\$ 1,657.25
	Scope : [001] Card No. : [030] VERIFIED AUTO THROTTLE CIRCUIT DISPLAYS POWER					
56	<u>Corrective Action</u> Additional time for ATS operational research. Labor, Standard, In House Summary Charge (Regular) Note: [ 04:11 HR ] <u>Charges Summary</u>		1.00EA	1.00	\$ 439.25000 EA	\$ 439.25
	Parts & Materials Labor, Standard, In House					\$ 5,606.43 \$ 35,873.25

Sub Total:					\$ 41,479.68
Total:					[USD] \$ 41,479.68
Balance:					[USD] \$ 41,479.68